

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/22/2023

Submitted Date:

06/22/2023

Document Number:

701602597

FIELD INSPECTION FORM

Loc ID: 313962 Inspector Name: SCHURE, KYM On-Site Inspection: 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 76840
Name of Operator: SCHNEIDER ENERGY SERVICES INC
Address: P O BOX 889
City: FORT MORGAN State: CO Zip: 80701

Findings:

- 3 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Schneider, Jeff	970-867-9437/ (214) 244-3819	jeff@schneiderenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
282183	WELL	SI	01/01/2021	GW	087-08142	SMITH 1	PA

General Comment:

MIRU - PREPARING TO P&A
FORM 42 RECEIVED
OPERATOR CALLED SCHURE WHEN RIG BECAME AVAILABLE, WAIVE NOTIFICATION DATES PER K.S.

Inspected Facilities

Facility ID: 282183 Type: WELL API Number: 087-08142 Status: SI Insp. Status: PA

Cement

Cement Contractor

Contractor Name: _____

Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): _____

Cement Volume (sx): _____

Good Return During Job: _____

Cement Type: _____

Comment:

Corrective Action:

Date: _____

COGCC Comments

Comment	User	Date
P&A IN PROCESS DAY (1)	schureky	06/22/2023