

Inspection Photos

6/21/2023

Operator: D & G ROUSTABOUT SERVICE -
22370

Location Number: 322318
Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos

Operator Name: D & G ROUSTABOUT SERVICE - 22370

Location Number: 322318



Photo 1: Photos taken from the north end of the Location. Photos provide an overview of the site facing south and southwest.

Inspection Photos

Operator Name: D & G ROUSTABOUT SERVICE - 22370

Location Number: 322318



Photo 2: Photos example showing Undesirable Plant Species such as Hoary cress (light green plants, photo left) bindweed, redstem filaree, knotweed, etc... establishing on the Location. Ongoing weed management activities insufficient.

Inspection Photos

Operator Name: D & G ROUSTABOUT SERVICE - 22370

Location Number: 322318



Photo 3: Photo example showing Undesirable Plant Species such as Hoary cress (light green plants, photo left) bindweed, redstem filaree, knotweed, etc... establishing on the Location.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Operator Name: D & G ROUSTABOUT SERVICE - 22370

Location Number: 322318



Photo 4: Photos show operator's attempt to comply with Rule 1002.c. Photos show erosion logs placed at the base of soil stockpiles on the Location have not been installed in accordance with good engineering practices, or maintained in proper functioning condition.

Inspection Photos

Operator Name: D & G ROUSTABOUT SERVICE - 22370

Location Number: 322318



Photo 5: See comment under photo 4.

Inspection Photos

Operator Name: D & G ROUSTABOUT SERVICE - 22370

Location Number: 322318



Photo 6: Surface equipment remaining on Location.

Inspection Photos

Operator Name: D & G ROUSTABOUT SERVICE - 22370

Location Number: 322318



Photo 7: Photo right 1994 USGS Historic Aerial imagery. Photo right 2011 Google Earth Aerial Imagery. Photos show presence of a historic pit located to the west of the tank facility.