


**Genesis
Moore 3-11
Location # 315693**



Location and stored equipment



Location well head



**Genesis
Moore 3-11
Location # 315693**



Recent photo of tank battery and open pit



Previous inspection photo of tank battery and open pit

**Genesis
Moore 3-11
Location # 315693**



Line from production tank had recently been opened to the unregistered pit behind the tank. Fluid and stained material on ground.



Line from production tank had recently been opened to the unregistered pit behind the tank. Fluid and stained material on ground.

**Genesis
Moore 3-11
Location # 315693**



Line from production tank had recently been opened to the unregistered pit behind the tank. Fluid and stained material on ground.




Line from production tank had recently been opened to the unregistered pit behind the tank. Fluid and stained material on ground.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

**Genesis
Moore 3-11
Location # 315693**



Recent photo of tank lacking proper labeling



Previous inspection of tank lacking proper labeling



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Genesis
Moore 3-11
Location # 315693



Recent photo of debris



Previous inspection photo of debris



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

**Genesis
Moore 3-11
Location # 315693**



Recent photo of bucket with fluid and debris



Previous inspection photo of bucket with fluid and debris

**Genesis
Moore 3-11
Location # 315693**



Recent photo of stored equipment and open hole for wildlife.



Previous inspection photo of stored equipment and open hole for wildlife.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

**Genesis
Moore 3-11
Location # 315693**



Recent photo of debris



Previous inspection of debris



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

**Genesis
Moore 3-11
Location # 315693**



Recent photo of debris



Previous inspection of debris



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

**Genesis
Moore 3-11
Location # 315693**



Recent photo of stored equipment and open holes for wildlife



Previous inspection photo of stored equipment and open holes for wildlife

Genesis
Moore 3-11
Location # 315693



Recent photo of battery signage is still not correct



Previous inspection of battery signage not correct



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

**Genesis
Moore 3-11
Location # 315693**



Stained material near well head and weeds.



Guard is missing from pump jack, safety issue.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Genesis
Moore 3-11
Location # 315693



Staining, bucket and debris



Electrical wires on the ground



**Genesis
Moore 3-11
Location # 315693**



Stored equipment and Electrical wires on the ground



Throughout location is covered with weeds.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

**Genesis
Moore 3-11
Location # 315693**



Recent photo of pipe on top of tank with a valve on it now



Previous inspection of pipe on top of tank with out a valve

Genesis
Moore 3-11
Location # 315693



Random debris



Noxious weeds



Genesis
Moore 3-11
Location # 315693



Weeds and well signage lacking information



Recent photo of debris



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources