

**Inspection Photos**  
**Location Name: CAERUS PICEANCE LLC 07EB Pad**  
**Location ID: 334883**



Jun 23, 2023 at 9:45:25 AM  
CO



Jun 23, 2023 at 9:45:34 AM  
CO

**Photo # 1540 From entrance to location**

**Photo # 1541 From entrance to location**

**Inspection Photos**  
**Location Name: CAERUS PICEANCE LLC 07EB Pad**  
**Location ID: 334883**



**Photo # 1542 Location**



**Photo # 1543 Location**



**Inspection Photos**  
**Location Name: CAERUS PICEANCE LLC 07EB Pad**  
**Location ID: 334883**



**Photo # 1544 Location**



**Photo # 1565 Debris**



**Inspection Photos**  
**Location Name: CAERUS PICEANCE LLC 07EB Pad**  
**Location ID: 334883**



**Photo # 9521 From Inspection 708900689 conducted on 06/05/2023 Unmarked deadman**



**Photo # 1548 Unmarked deadman**



**Inspection Photos**  
**Location Name: CAERUS PICEANCE LLC 07EB Pad**  
**Location ID: 334883**



**Photo # 9523 From Inspection 708900689 conducted on 06/05/2023 Same unmarked deadman from a different angle**



**Photo # 1551 Same unmarked deadman from a different angle**



**Inspection Photos**  
**Location Name: CAERUS PICEANCE LLC 07EB Pad**  
**Location ID: 334883**



**Photo # 1563 Same unmarked deadman/different angle**



**Photo # 1552 Unmarked deadman**



**Inspection Photos**  
**Location Name: CAERUS PICEANCE LLC 07EB Pad**  
**Location ID: 334883**



**Photo # 1553 Unmarked deadman from a different angle**



**Photo # 1568 Debris**



**Inspection Photos**  
**Location Name: CAERUS PICEANCE LLC 07EB Pad**  
**Location ID: 334883**



**Photo # 1569 Debris**



**Photo # 1570 Debris**

