Inspection Photos
Location Name: CAERUS PICEANCE LLC H18E Pad
Location ID: 323940

Photo # 1654 From entrance to location

Photo # 1655 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC H18E Pad
Location ID: 323940

Photo # 1656 Location

Photo # 1657 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC H18E Pad
Location ID: 323940

Photo # 1661 Weeds/undesirable plant species in secondary containment

Photo # 1662 Weeds/undesirable plant species in secondary containment

Inspection Photos
Location Name: CAERUS PICEANCE LLC H18E Pad
Location ID: 323940

Photo # 1663 Weeds/undesirable plant species in secondary containment

Photo # 1664 Weeds/undesirable plant species in secondary containment

Inspection Photos
Location Name: CAERUS PICEANCE LLC H18E Pad
Location ID: 323940

Photo # 1665 Weeds/undesirable plant species in secondary containment