

Inspection Photos

Location Name: GREELEY-ROTHE FEDERAL 16-1 PAD

Location ID: 454188




Photo 1: Wellhead Sign



Photo 2: Stained soil

Inspection Photos

Location Name: GREELEY-ROTHE FEDERAL 16-1 PAD

Location ID: 454188



Colorado Oil & Gas Conservation Commission
40.42417, -104.83349, 1476.4m, 358°
Jun 15, 2023 14:57:08

Photo 3: Stained soil



Colorado Oil & Gas Conservation Commission
40.42477, -104.83361, 1477.8m, 40°
Jun 15, 2023 14:58:52

Photo 4: Wellhead sign

Inspection Photos
Location Name: GREELEY-ROTHER FEDERAL 16-1 PAD
Location ID: 454188




Photo 5: Weeds removed



Photo 6: Stained soil removed

Inspection Photos

Location Name: GREELEY-ROTHER FEDERAL 16-1 PAD

Location ID: 454188



Photo 7: Weeds removed