

Final Reclamation Inspection

May 31st, 2023

Operator: PDC ENERGY INC - 69175

Location ID: 307211

Inspection Document #: 701900897

SESW Section 25 T5N R68W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Ryan 25-BU
Location ID: 307211




Photo 1. 2021 aerial imagery of the well pad and tank battery (north is up).

Inspection Photos
Location Name: Ryan 25-BU
Location ID: 307211



Photo 2. Overview photo of the tank battery taken at ground level from the southern edge facing north.

Inspection Photos
Location Name: Ryan 25-BU
Location ID: 307211



Photo 3. Cardinal photos taken from the middle of the tank battery.
Left photo facing north, right photo facing east.

Inspection Photos
Location Name: Ryan 25-BU
Location ID: 307211



Photo 4. Cardinal photos taken from the middle of the tank battery. Left photo facing south, right photo facing west. Note: tank battery falls within an alfalfa but has 80% perennial grass cover.

Inspection Photos
Location Name: Ryan 25-BU
Location ID: 307211



Photo 5. Overview photo of the well pad taken at ground level from the western edge facing northeast.

Inspection Photos
Location Name: Ryan 25-BU
Location ID: 307211



Photo 6. Cardinal photos taken from the middle of the well pad. Left photo facing north, right photo facing east.

Inspection Photos
Location Name: Ryan 25-BU
Location ID: 307211



Photo 7. Cardinal photos taken from the middle of the well pad. Left photo facing south, right photo facing west. Note: well pad appears consistent with adjacent crop reference area (see photo 8).

Inspection Photos
Location Name: Ryan 25-BU
Location ID: 307211



Photo 8. Reference photo.