

Inspection Photos

Loc: 484496

Operator: NUEVIDA RESOURCES LLC

Inspection Date: 6/15/2023



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Loc: 484496 | Date: 6/15/2023

Inspection Photos



Photo 1. View of test hole for topsoil evaluation. Taken at the Ardourel tank pad Lat/Long:37.09858,-107.76772. It appears there is 8-10" soil horizon that should be salvaged.



Photo 2. Northeast corner of the location facing southwest. It appears topsoil was being salvaged around 6-8" in some areas and less in other areas but salvaging was still ongoing.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 484496 | Date: 6/15/2023

Inspection Photos



Photo 3. The soil Data (#5) which is where the Ardourel tank Pad is located. There is a Bss1 horizon that extends to about 11”.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 484496 | Date: 6/15/2023

Inspection Photos



Photo 4. The soil Data (#27) which is where the Ardourel well Pad is located. There is a BA horizon that extends to about 14”.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Loc: 484496 | Date: 6/15/2023