

Inspection Photos

API: 071-07767

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 6/21/2023



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07767 | Date: 6/21/2023

Inspection Photos



Photo 1. Facing west at the location. The area of erosion has been repaired and seeded. Vegetation will need to establish for long term stabilization.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07767 | Date: 6/21/2023

Inspection Photos



Photo 2. Facing west at the location. The two track road continues past the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07767 | Date: 6/21/2023

Inspection Photos



Photo 3. Facing northwest toward the reclaimed fill slope.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07767 | Date: 6/21/2023