

# Inspection Photos

API: 071-08606

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 6/21/2023



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-08606 | Date: 6/21/2023

## Inspection Photos



**Photo 1.** Facing west along the main road in Jaroso Canyon. There has been road base applied to this area of the road where stormwater use to accumulate.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08606 | Date: 6/21/2023



## Inspection Photos



**Photo 2.** Facing southeast along the road. There has been road base applied to this area of the road where stormwater use to accumulate and culvert is maintained.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08606 | Date: 6/21/2023

## Inspection Photos



**Photo 3.** Further along the road. The culverts along the road have been cleaned out and maintained.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08606 | Date: 6/21/2023



## Inspection Photos



**Photo 4.** Facing north at the TA wellsite. There were other culverts further along the road that have been maintained.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-08606 | Date: 6/21/2023