

Inspection Photos

6/21/2023

Operator: UTAH GAS OP LTD DBA UTAH GAS

CORP #10539

Location Number: 322479

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP #10539

Location Number: 322479



Photo 1: Photos taken from the stream crossing at the access road. Photo shows degradation issues have been repaired, and the culvert BMP has been maintained.

Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP #10539

Location Number: 322479



Photo 2: Photo shows areas where runoff from the northern fork of the access road appears to be discharging at the same point where erosion degradation at the road was observed. This area of the access road remains at risk to further degradation and maintenance/additional BMPs are advised.

Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP #10539

Location Number: 322479



Photo 3: Photos 3-4 taken from the south end of the Location. Photos provide an overview of the Location from west, northwest, northeast to east. Vegetation observed within photos are predominantly Undesirable Plant Species such as Bindweed, Knotweed, and Russian thistle.

Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP #10539

Location Number: 322479



Photo 4: See comments under photo 3. Photo also shows surface equipment remaining-records show well was PA 5/2021, all surface equipment was required to be removed within 3 months of abandonment.

Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP #10539

Location Number: 322479



Photo 5: Photos examples showing surface equipment remaining on Location. Photo left shows riser remaining from what appeared to have been separator equipment. Meter shed and associated lines/risers also shown in photo. Photo right shows former well site with a flowline riser remaining. Records show well was PA 5/2021; all surface equipment was required to be removed within 3 months of abandonment.

Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP #10539

Location Number: 322479



Photo 6: Photos examples showing vegetation observed is predominantly Undesirable Plant Species such as Bindweed, Knotweed, and Russian thistle.

Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP #10539

Location Number: 322479



Photo 7: Photo shows anchor equipment remaining on the Location. Well has been P&A, all surface equipment should have been removed.

Inspection Photos

Operator Name: UTAH GAS OP LTD DBA UTAH GAS CORP #10539

Location Number: 322479



Photo 8: Fill slopes. Location requires compaction alleviation, recontouring/regrading and reclamation.