

TEP ROCKY MOUNTAIN LLC, WILLIAMS-66S96W/32SENE
Location #335492
Date: 6/22/2023



Jun 22, 2023 at 14:04:13



Jun 22, 2023 at 14:04:40

SE Corner of Location – Photo #04709

NE Corner of Location – Photo #04710

TEP ROCKY MOUNTAIN LLC, WILLIAMS-66S96W/32SENE
Location #335492
Date: 6/22/2023



NW Corner of Location – Photo #04711



SW Corner of Location – Photo #04712

TEP ROCKY MOUNTAIN LLC, WILLIAMS-66S96W/32SENE
Location #335492
Date: 6/22/2023



Wellheads – Photo #04713



Separators – Photo #04715

TEP ROCKY MOUNTAIN LLC, WILLIAMS-66S96W/32SENE

Location #335492

Date: 6/22/2023



Tank Battery – Photo #04716



Open-Ended Load Line – Photo #04717

TEP ROCKY MOUNTAIN LLC, WILLIAMS-66S96W/32SENE

Location #335492

Date: 6/22/2023



Jun 22, 2023 at 14:08:10
3555 CR-215
Parachute CO 81635
United States



Jun 22, 2023 at 14:09:02
3555 CR-215
Parachute CO 81635
United States

Unsecured Door on Separator – Photo #04718

Location Lacks Stabilization – Photo #04721

TEP ROCKY MOUNTAIN LLC, WILLIAMS-66S96W/32SENE

Location #335492

Date: 6/22/2023



Location Lacks Stabilization – Photo #04722



Insufficient Vehicle Tracking BMPs at Location Entrance/Exit – Photo #04720