

# TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/32NESE

Location #335240

Date: 6/22/2023



**NE Corner of Location – Photo #04725**



**SE Corner of Location – Photo #04726**

# TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/32NESE

Location #335240

Date: 6/22/2023



**SW Corner of Location – Photo #04727**

**NW Corner of Location – Photo #04728**

# TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/32NESE

Location #335240

Date: 6/22/2023



Wellheads – Photo #04729




Separators – Photo #04714

# TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/32NESE

Location #335240

Date: 6/22/2023



Tank Battery – Photo #04716

Open-Ended Load Line – Photo #04717

# TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/32NESE

Location #335240

Date: 6/22/2023



**Location Lacks Stabilization – Photo #04736**



**Access Road Lacks Stabilization – Photo #04739**

# TEP ROCKY MOUNTAIN LLC, UNOCAL-66S96W/32NESE

Location #335240

Date: 6/22/2023



**Insufficient Vehicle Tracking BMPs at Location  
Entrance/Exit – Photo #04737**