

CAERUS PICEANCE LLC, TIPPING-67S96W/34NWNW

Location #334094

Date: 6/23/2023



NW Corner of Location – Photo #04781

SW Corner of Location – Photo #04782

CAERUS PICEANCE LLC, TIPPING-67S96W/34NWNW

Location #334094

Date: 6/23/2023



SE Corner of Location – Photo #04783



NE Corner of Location – Photo #04784

CAERUS PICEANCE LLC, TIPPING-67S96W/34NWNW

Location #334094

Date: 6/23/2023



Wellheads – Photo #04788



Separators – Photo #04785



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

CAERUS PICEANCE LLC, TIPPING-67S96W/34NWNW

Location #334094

Date: 6/23/2023



Tank Battery – Photo #04789



Open-Ended Line – Photo #04790

CAERUS PICEANCE LLC, TIPPING-67S96W/34NWNW

Location #334094

Date: 6/23/2023



Open-Ended Line – Photo #04791



Open-Ended Line – Photo #04792