

Inspection Photos
Location Name: MCKINNEY #1-9
Location ID: 320519



Photo# 1 Crude tank.



Photo# 2 P/W and crude tanks.

Inspection Photos
Location Name: MCKINNEY #1-9
Location ID: 320519



Photo# 3 Separator.



Photo# 4 Well head.