

Inspection Photos

Location Name: KEHN USX AA-66N63W /1NWNW

Location #: 310894



Photo #1

Kehn USX AA 01-04 (05-123-27195) Wellsite

Shut-In | SI



Photo #2

Kehn USX AA 01-04, 01-06 Battery site

Inactive | Shut-down

Inspection Photos

Location Name: KEHN USX AA-66N63W /1NWNW

Location #: 310894



Photo #3

Kehn USX AA 01-04, 01-06 Battery site

Inactive | Shut-down

Tank(s): SE corner



Photo #4

Kehn USX AA 01-04, 01-06 Battery site

Inactive | Shut-down

Separator(s), ECD(s)

Inspection Photos

Location Name: KEHN USX AA-66N63W /1NWNW

Location #: 310894



Photo #5

Kehn USX AA 01-04, 01-06 Battery site

Inactive | Shut-down

Battery sign



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources