

**Scout Energy Management LLC
Associated Unit C 1
Location #314494**



Vehicle tracking pad installed since last inspection



Vehicle tracking pad installed since last inspection

**Scout Energy Management LLC
Associated Unit C 1
Location #314494**



Location view from Southeast corner



Location view from Northeast corner

**Scout Energy Management LLC
Associated Unit C 1
Location #314494**



Location view from Northwest corner



Location view from Southwest corner