

Scout Energy Management LLC
A C McLaughlin 51X
Location #314695



Vehicle tracking pad installed since last inspection



Wellhead sign. No tank battery.

**Scout Energy Management LLC
A C McLaughlin 51X
Location #314695**



Location view from Southeast corner



Location view from Northeast corner

**Scout Energy Management LLC
A C McLaughlin 51X
Location #314695**



Location view from Northwest corner



Location view from Southwest corner