

Scout Energy Management LLC
A. C. McLaughlin 83X
Location #316472



Vehicle tracking pad installed since last inspection



Wellhead sign. No tank battery.

**Scout Energy Management LLC
A. C. McLaughlin 83X
Location #316472**



BMP repair since last inspection



BMP repair since last inspection

**Scout Energy Management LLC
A. C. McLaughlin 83X
Location #316472**



BMP repair since last inspection



BMP repair since last inspection

**Scout Energy Management LLC
A. C. McLaughlin 83X
Location #316472**



Location view from Southeast corner



Location view from Northeast corner

**Scout Energy Management LLC
A. C. McLaughlin 83X
Location #316472**



Location view from Northwest corner



Location view from Southwest corner