

VISION ENERGY LLC, LIPAN WASH-U2N2W/16NESW

Location #312553

Date: 6/27/2023



NW Corner of Location – Photo #04837



SW Corner of Location – Photo #04838

VISION ENERGY LLC, LIPAN WASH-U2N2W/16NESW

Location #312553

Date: 6/27/2023



SE Corner of Location – Photo #04844



NE Corner of Location – Photo #04849

VISION ENERGY LLC, LIPAN WASH-U2N2W/16NESW

Location #312553

Date: 6/27/2023



Unused Equipment Stored on Location – Photo #04839



Wildlife Entry Hazard – Photo #04840

VISION ENERGY LLC, LIPAN WASH-U2N2W/16NESW

Location #312553

Date: 6/27/2023



Unprotected Soil Stockpile – Photo #04841



Unprotected Soil Stockpile – Photo #04842

VISION ENERGY LLC, LIPAN WASH-U2N2W/16NESW

Location #312553

Date: 6/27/2023



Unprotected Soil Stockpile – Photo #04845



Debris – Photo #04847

VISION ENERGY LLC, LIPAN WASH-U2N2W/16NESW

Location #312553

Date: 6/27/2023



Debris – Photo #04848