

Inspection Photos
Location Name: CAERUS PICEANCE LLC F17E Pad
Location #: 334793



Photo # 2025 From entrance to location



Photo # 2026 From entrance to location

Inspection Photos
Location Name: CAERUS PICEANCE LLC F17E Pad
Location #: 334793



Photo # 2027 Location



Photo # 2028 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC F17E Pad
Location #: 334793



Photo # 2029 Location



Photo # 2032 Improperly marked deadman

Inspection Photos
Location Name: CAERUS PICEANCE LLC F17E Pad
Location #: 334793



Photo # 2030 Weeds/undesirable plant species



Photo # 2031 Weeds/undesirable plant species

Inspection Photos
Location Name: CAERUS PICEANCE LLC F17E Pad
Location #: 334793



Photo # 2037 Weeds/undesirable plant species



Photo # 2038 Weeds/undesirable plant species

Inspection Photos
Location Name: CAERUS PICEANCE LLC F17E Pad
Location #: 334793



Photo # 2040 Weeds/undesirable plant species




Photo # 2042 Weeds/undesirable plant species