

Inspection Photos  
Location Name: Brand 1  
Location ID: 311305



Colorado Oil & Gas Conservation Commission  
40.10742, -104.80286, 4849.1ft, 260°  
06/27/2023 14:41:51



Colorado Oil & Gas Conservation Commission  
40.10747, -104.80291, 4844.4ft, 174°  
06/27/2023 14:40:00

Photo 1 WH sign.

Photo 2 WH.

**Inspection Photos**  
**Location Name: Brand 1**  
**Location ID: 311305**



**Photo 3 Pump Jack.**

**Photo 4 unused propane tank next to pump jack.**

**Inspection Photos**  
**Location Name: Brand 1**  
**Location ID: 311305**



**Photo 5 Unused Flow line with valve next to pump jack no LOTO.**

**Photo 6 unused Flow line next to pump jack, no LOTO.**

**Inspection Photos**  
**Location Name: Brand 1**  
**Location ID: 311305**



**Photo 7 Unused Steel barrel next to pump jack.**

**Photo 8 unused plastic barrel next to pump jack.**

**Inspection Photos**  
**Location Name: Brand 1**  
**Location ID: 311305**



**Photo 9 stained soil by the WH.**



**Photo 10 stained soil by the WH.**

**Inspection Photos**  
**Location Name: Brand 1**  
**Location ID: 311305**



**Photo 11 stained soil in the pump jack frame.**



**Photo 12 stained soil in the pump jack frame under gas engine.**

**Inspection Photos**  
**Location Name: Brand 1**  
**Location ID: 311305**



**Photo 13 stained soil in the pump jack frame.**



**Photo 14 stained soil in the pump jack frame under gas engine.**

Inspection Photos  
Location Name: Brand 1  
Location ID: 311305



Photo 15 TB sign.

Photo 16 TB

**Inspection Photos**  
**Location Name: Brand 1**  
**Location ID: 311305**



**Photo 17 No tank volume of PW placard is peeling.**

**Photo 18 No volume on PW tank, placard faded and peeling.**

Inspection Photos  
Location Name: Brand 1  
Location ID: 311305



Photo 19 Marked flow line no LOTO.



Photo 20 Marked flow line no LOTO.