

Storm Water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC GUCCINI Pad
Location ID: 335083



Location Overview: Location is in close proximity to Rule 411a Surface Water External Buffer & approximately 300 yards from Mamm Creek. Location is within High Priority/Density/Black Bear Habitat areas & within close proximity to NSO Habitat area.

Section/Township/Range: 20 6S92W



Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC GUCCINI Pad
Location ID: 335083



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC GUCCINI Pad
Location ID: 335083



Photo # 1987 Sediment trap needs maintenance



Photo # 1988 Sediment trap needs maintenance

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC GUCCINI Pad
Location ID: 335083



Photo # 1989 Sediment trap needs maintenance



Photo # 2005 Erosion & transport of sediment off location/sediment choking of vegetation

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC GUCCINI Pad
Location ID: 335083



Photo # 1992 Erosion & transport of sediment off location/sediment choking of vegetation



Photo # 1993 Erosion & transport of sediment off location/sediment choking of vegetation

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC GUCCINI Pad
Location ID: 335083



Photo # 1994 Erosion & transport of sediment off location/sediment choking of vegetation



Photo # 1995 Erosion & transport of sediment off location/sediment choking of vegetation

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC GUCCINI Pad
Location ID: 335083



Photo # 1996 Erosion & transport of sediment off location/sediment choking of vegetation



Photo # 1997 Erosion & transport of sediment off location/sediment choking of vegetation

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC GUCCINI Pad
Location ID: 335083



Photo # 1999 Erosion & transport of sediment off location/sediment choking of vegetation



Photo # 2000 Erosion & transport of sediment off location/sediment choking of vegetation

Storm water Management and Erosion control
Location Name: TEP ROCKY MOUNTAIN LLC GUCCINI Pad
Location ID: 335083



Photo # 2001 Erosion & transport of sediment off location/sediment choking of vegetation



Photo # 2002 Erosion & transport of sediment off location/sediment choking of vegetation