

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WEINREIS A Pad

Location ID: 335548



Photo # 1783 From entrance to location



Photo # 1784 Location



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WEINREIS A Pad

Location ID: 335548



Photo # 1785 Location



Photo # 1786 Location





## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WEINREIS A Pad

Location ID: 335548



Photo # 1787 Location



Photo # 1796 Stained gravel in secondary containment



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WEINREIS A Pad

Location ID: 335548



**Photo # 1797 Stained gravel in secondary containment**



**Photo # 1798 Stained gravel in secondary containment**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WEINREIS A Pad

Location ID: 335548



**Photo # 1799 Stained gravel in secondary containment**



**Photo # 1800 Stained gravel in secondary containment**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WEINREIS A Pad

Location ID: 335548



**Photo # 1801 Stained gravel in secondary containment**



**Photo # 1802 Unused equipment/ECD is completely disconnected**



## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WEINREIS A Pad

Location ID: 335548



**Photo # 1803 Unused equipment/ECD is completely disconnected**