

Inspection Photos  
Location Name: Jean Ann 25-22  
Location ID: 305408



Photo 1: Tank Battery Signs



Photo 2: No well sign displayed

**Inspection Photos**  
**Location Name: Jean Ann 25-22**  
**Location ID: 305408**



Colorado Oil & Gas Conservation Commission  
40.38876, -104.88355, 1522.6m, 5°  
Jun 28, 2023 15:30:41

**Photo 3: Trash, stained soil treated UNKNOWN**



Colorado Oil & Gas Conservation Commission  
40.38877, -104.88367, 1521.5m, 211°  
Jun 28, 2023 15:30:52

**Photo 4: Unused equipment**

**Inspection Photos**  
**Location Name: Jean Ann 25-22**  
**Location ID: 305408**



**Photo 5: Unused equipment**



**Photo 6: Unused equipment**

**Inspection Photos**  
**Location Name: Jean Ann 25-22**  
**Location ID: 305408**



**Photo 7: Unused equipment**



**Photo 8: Unused equipment**

**Inspection Photos**  
**Location Name: Jean Ann 25-22**  
**Location ID: 305408**



**Photo 9: Unused equipment**