


Scout Energy Management LLC
A.C. McLaughlin 73X
Location #315337



Entrance tracking pad installed since last inspection



Well sign. No tank battery.

**Scout Energy Management LLC
A.C. McLaughlin 73X
Location #315337**



Location view from Southeast corner

Location view from Northeast corner

**Scout Energy Management LLC
A.C. McLaughlin 73X
Location #315337**



Location view from Northwest corner



Location view from Southwest corner