

Scout Energy Management LLC
U P 3-34
Location #314375



Tracking pad installed since last inspection off Hwy 64.



Tracking pad installed at Southwest location entrance since last inspection.

Scout Energy Management LLC
U P 3-34
Location #314375



Tracking pad installed at Northwest location entrance since last inspection.



Well sign. No tank battery.

Scout Energy Management LLC
U P 3-34
Location #314375



Location view from Southeast corner



Location view from Northeast corner

Scout Energy Management LLC
U P 3-34
Location #314375



Location view from Northwest corner



Location view from Southwest corner