

Inspection Photos
Location Name: Amen #1
Location ID: 319144



Photo 1: Wellhead Sign



Photo 2: Bucket removed

Inspection Photos
Location Name: Amen #1
Location ID: 319144



Photo 3: Stained soil, weeds



Photo 4: Stained soil, weeds

Inspection Photos
Location Name: Amen #1
Location ID: 319144



Photo 5: Stained soil removed



Photo 6: Equipment removed, weeds

Inspection Photos
Location Name: Amen #1
Location ID: 319144



Photo 7: Bucket containing animal



Photo 8: Animal in unknown liquid

Inspection Photos
Location Name: Amen #1
Location ID: 319144



Photo 9: Animal inside bucket of unknown liquid



Photo 10: Tank removed, weeds

Inspection Photos
Location Name: Amen #1
Location ID: 319144



Photo 11: Appears to have sold product



Photo 12: Appears to have sold product

Inspection Photos
Location Name: Amen #1
Location ID: 319144



Photo 13: Appears to have sold product