

Inspection Photos
Location Name: Pronghorn 11-14-12HZ
Location ID: 427785



Photo 1 – Pumping Unit



Photo 2 – Wellhead

Inspection Photos
Location Name: Pronghorn 11-14-12HZ
Location ID: 427785



Photo 3 – Wellhead Sign



Photo 4 – ECD

Inspection Photos
Location Name: Pronghorn 11-14-12HZ
Location ID: 427785



Photo 5 – Pipe Rack



Photo 6 – Tank Battery

Inspection Photos
Location Name: Pronghorn 11-14-12HZ
Location ID: 427785




Photo 7 – North Tank – Capacity Label



Photo 8 – Middle Tank – NFPA, Content, and Capacity Labels

Inspection Photos
Location Name: Pronghorn 11-14-12HZ
Location ID: 427785



Photo 9 – South Tank – Capacity and Content Labels



Photo 10 – Tank Battery Signs

Inspection Photos
Location Name: Pronghorn 11-14-12HZ
Location ID: 427785



Photo 11 – Gas Meter



Photo 12 – Separators

Inspection Photos
Location Name: Pronghorn 11-14-12HZ
Location ID: 427785



Photo 13 – Gas Meter and Tank Battery