

# Final Reclamation Inspection

May 31st, 2023

Operator: PDC ENERGY INC - 69175

Location ID: 328363

Inspection Document #: 701900901

SWSW Section 21 T5N R64W

Corey McDonough  
Reclamation Contractor, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Elder 13-21  
Location ID: 328363



**Photo 1.** 2019 aerial imagery of the well pad, tank battery and reference area.  
Note: disturbance falls within the Rangeview Ranches subdivision.



Inspection Photos  
Location Name: Elder 13-21  
Location ID: 328363



**Photo 2.** Overview photo of the well pad taken at ground level from the eastern edge facing west.



Inspection Photos  
Location Name: Elder 13-21  
Location ID: 328363



**Photo 3.** Cardinal photos taken from the middle of the well pad. Left photo facing north, right photo facing east.



Inspection Photos  
Location Name: Elder 13-21  
Location ID: 328363



**Photo 4.** Cardinal photos taken from the middle of the well pad. Left photo facing south, right photo facing west. Note: well pad is dominated by a weedy annual, cheatgrass.



Inspection Photos  
Location Name: Elder 13-21  
Location ID: 328363



**Photo 5.** Overview photo of the tank battery taken at ground level from the western edge facing east.



Inspection Photos  
Location Name: Elder 13-21  
Location ID: 328363



**Photo 6.** Cardinal photos taken from the middle of the tank battery.  
Left photo facing north, right photo facing east.



Inspection Photos  
Location Name: Elder 13-21  
Location ID: 328363



**Photo 7.** Cardinal photos taken from the middle of the tank battery. Left photo facing south, right photo facing west. Note: Tank battery is dominated by cheatgrass.



Inspection Photos  
Location Name: Elder 13-21  
Location ID: 328363



**Photo 8.** Well pad and tank battery reference area.