

# Final Reclamation Inspection

May 31st, 2023

Operator: PDC ENERGY INC - 69175

Location ID: 328535

Inspection Document #: 701900903

NESW Section 8 T5N R64W


Corey McDonough  
Reclamation Contractor, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources



**Photo 1.** 2019 aerial imagery of the well pad. Note: tank battery (not pictured) is associated with the PJ 3 well API #123-16111.

Inspection Photos  
Location Name: PJ 2  
Location ID:328535



**Photo 2.** Overview photo of the well pad taken at ground level from the western edge facing east.



Inspection Photos  
Location Name: PJ 2  
Location ID:328535



**Photo 3.** Cardinal photos taken from the middle of the well pad. Left photo facing north, right photo facing east.

Inspection Photos  
Location Name: PJ 2  
Location ID:328535



**Photo 4.** Cardinal photos taken from the middle of the well pad. Left photo facing south, right photo facing west. Note: well pad falls within a large pasture filled with cattle. Area has been trampled by cattle, bare area does not appear to be related to oil and gas operations/reclamation.