

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/27/2023

Submitted Date:

06/29/2023

Document Number:

701007118**FIELD INSPECTION FORM**Loc ID 321798 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 51065Name of Operator: LOEB LLC\* HERMAN LAddress: P O BOX 838City: LAWRENCEVILLE State: IL Zip: 62439**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Pelton, Shane	620-617-5870	shane@loeboil.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
208047	WELL	TA	04/10/2014	SI	017-06982	HAROLD 24-13 3	PA

**General Comment:**P&A Inspection

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Trail through farm ground		
Corrective Action	L	Date:	

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Lease sign by cathodic rectifier		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:  Date:

Overall Good: ☒

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 208047 Type: WELL API Number: 017-06982 Status: TA Insp. Status: PA**Cement**Cement ContractorContractor Name: Hurricane Oilfield

Contractor Phone: \_\_\_\_\_

Surface Casing

Cement Volume (sx): \_\_\_\_\_

Circulate to Surface: \_\_\_\_\_

Cement Fall Back: \_\_\_\_\_

Top Job, 1" Volume: \_\_\_\_\_

Intermediate Casing

Cement Volume (sxs): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Production Casing

Cement Volume (sx): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Plugging OperationsDepth Plugs(feet range): 2120/2000/1340/491Cement Volume (sx): 345 SXSGood Return During Job: YESCement Type: Class H NeatComment:

PEAK WIRELINE, STERLING OILFIELD SERVICES, HALDE WATER, HURRICANE OILFIELD SERVICES. MIRU HURRICANE, PUMP 75 SXS THRU CICR W/25 SXS ON TOP. MIRU STERLING, POOH W/TBG. MIRU PEAK, RIH W/GUN PERF @ 1340'. MIRU STERLING, RIH W/CICR TO 1240'. MIRU HURRICANE, PUMP 50 SXS THRU W/10 SXS ON TOP. MIRU STERLING, POOH W/TBG. MIRU PEAK, RIH W/GUN PERF @ 491'. MIRU HURRICANE, RU TO CSG AND BULLHEAD 185 SXS CMT DOWN CSG W/CMT TO SFC.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass	Other	Pass			

Comment: Location and access are farmed over

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT