

Inspection Photos
Location Name: Leggett 1-5H
Location ID: 428225



Photo 1 – Wellhead



Photo 2 – Tank Battery

Inspection Photos
Location Name: Leggett 1-5H
Location ID: 428225



Photo 3 – Oily Waste and Debris



Photo 4 – Stained Soil

Inspection Photos
Location Name: Leggett 1-5H
Location ID: 428225



Photo 5 – Tank Battery Sign



Photo 6 – Heater Treater

Inspection Photos
Location Name: Leggett 1-5H
Location ID: 428225



Photo 7 – Gas Meter



Photo 8 – Weeds

Inspection Photos
Location Name: Leggett 1-5H
Location ID: 428225



Photo 9 – Weeds in I.R. Area



Photo 10 – Weeds in I.R. Area

Inspection Photos
Location Name: Leggett 1-5H
Location ID: 428225



Photo 11 – Weeds in I.R. Area



Photo 12 – Weeds in I.R. Area