

Inspection Photos

ID: 150131

Operator: STRACHAN EXPLORATION INC

Inspection Date: 6/29/2023



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 150131 | Date: 6/29/2023

Inspection Photos



Photo 1. 2015 Aerial image showing the SALT LAKE UNIT abandoned location and associated facility.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 150131 | Date: 6/29/2023

Inspection Photos



Photo 2. Facing east toward the SALT LAKE UNIT abandoned location. The semi truck with the gravel and contaminated soil still remains parked in the same position as previous inspection conducted 4/2022. The location still remains unreclaimed with undesirable weeds.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 150131 | Date: 6/29/2023

Inspection Photos



Photo 3. Facing south at the location. The location consists of undesirable weeds and areas of bare soil.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 150131 | Date: 6/29/2023

Inspection Photos



Photo 4. Facing south at the location. The location consists of undesirable weeds and areas of bare soil.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 150131 | Date: 6/29/2023

Inspection Photos



Photo 5. View of groundcover shows undesirable weeds (Kochia sp.) which were observed throughout the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 150131 | Date: 6/29/2023

Inspection Photos



Photo 6. Facing south toward the surrounding undisturbed pasture which consists of a uniform native Blue grama grassland.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 150131 | Date: 6/29/2023

Inspection Photos



Photo 7. 2015 Aerial image showing the SALT LAKE UNIT associated battery facility. The abandoned access road that goes to the abandoned location needs to be reclaimed. The active road which travels east is in use for the FRAZEE #B-14-2 PR well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 150131 | Date: 6/29/2023

Inspection Photos



Photo 8. Facing east at the beginning of the access road from CR 27 to the Salt Lake Unit associated battery facility. The gates were removed and wire fence was put up.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 150131 | Date: 6/29/2023

Inspection Photos



Photo 9. The access road turns north toward the location and dead ends. The soils are compacted and the road has not been reclaimed. There are undesirable weeds and some native vegetation that have grown in but bare soils still remain.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 150131 | Date: 6/29/2023

Inspection Photos



Photo 10. Facing north along the access road near the location. There are noxious weeds, field bindweed in this area shown at red arrow.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 150131 | Date: 6/29/2023

Inspection Photos



Photo 11. Facing north at the location. There is mostly undesirable weeds in this area and some desirable vegetation was observed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 150131 | Date: 6/29/2023

Inspection Photos



Photo 12. North side of the location facing south. This area consists of bare soils and undesirable weeds.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 150131 | Date: 6/29/2023

Inspection Photos



Photo 13. Center of the location facing south. There are undesirable weeds throughout the location that need to be controlled.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

ID: 150131 | Date: 6/29/2023

Inspection Photos



Photo 14. View of groundcover shows undesirable weeds (Kochia sp.) which were observed throughout the location.



Inspection Photos



Photo 15. Facing east toward the surrounding undisturbed pasture which consists of a uniform native Blue grama grassland.

