

Inspection Photos

API: 061-06353

Operator: STRACHAN EXPLORATION

Inspection Date: 6/29/2023



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06353 | Date: 6/29/2023

Inspection Photos



Photo 1. Center of the location facing north. The location consists mostly of undesirable weeds and has not been reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06353 | Date: 6/29/2023

Inspection Photos



Photo 2. Center of the location facing south. The location consists mostly of undesirable weeds and has not been reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06353 | Date: 6/29/2023

Inspection Photos



Photo 3. Center of the location facing east. The location consists mostly of undesirable weeds and has not been reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06353 | Date: 6/29/2023

Inspection Photos



Photo 4. Center of the location facing west. The location consists mostly of undesirable weeds and has not been reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06353 | Date: 6/29/2023

Inspection Photos



Photo 5. View of groundcover shows undesirable weeds (Kochia sp.).



Inspection Photos



Photo 6. Facing north toward the surrounding undisturbed pasture which consists of Blue grama, Sand drop seed, among other native species.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06353 | Date: 6/29/2023

Inspection Photos




Photo 6. FOR REFERENCE: 2005 aerial image shows the approximate disturbance area of the HELFRICH #1 location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06353 | Date: 6/29/2023