

CAERUS PICEANCE LLC – 10456

API# 05-045-13367 N.PARACHUTE #WF09D M14 596

API# 05-045-13404 N.PARACHUTE #WF10D M14 596

Inspection Date : 6/30/2023



Location overview looking SE



Tank battery

CAERUS PICEANCE LLC – 10456

API# 05-045-13367 N.PARACHUTE #WF09D M14 596

API# 05-045-13404 N.PARACHUTE #WF10D M14 596

Inspection Date : 6/30/2023



Pump housing



Separator

CAERUS PICEANCE LLC – 10456

API# 05-045-13367 N.PARACHUTE #WF09D M14 596

API# 05-045-13404 N.PARACHUTE #WF10D M14 596

Inspection Date : 6/30/2023



API# 05-045-13404 N.PARACHUTE #WF10D M14 596

Injection wellhead. Temporarily Abandoned.



API# 05-045-13367 N.PARACHUTE #WF09D M14 596

Injection wellhead. Temporarily Abandoned.