

Storm Water Management and Erosion control
Location Name: CAERUS PICEANCE LLC K33NW Pad
Location #: 334632



Location Overview: Location is within High Priority/Density/Black Bear Habitat areas & within close proximity to NSO Habitat area.
Section/Township/Range: 33 6S93W

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC K33NW Pad
Location #: 334632



North West corner of location.



North East corner of location.



South West corner of location.



South East corner of location.

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC K33NW Pad
Location #: 334632



**Photo # 2248 Lack of stabilization on cutslope
along lease road**



**Photo # 2249 Lack of stabilization on cutslope
along lease road**

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC K33NW Pad
Location #: 334632



**Photo # 2250 Lack of stabilization/erosion on
cutslope along lease road**



**Photo # 2252 Lack of stabilization/erosion on
cutslope along lease road**

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC K33NW Pad
Location #: 334632



**Photo # 2253 Lack of stabilization/erosion on
cutslope along lease road**



**Photo # 2254 Lack of stabilization/erosion on
cutslope along lease road**

Storm water Management and Erosion control
Location Name: CAERUS PICEANCE LLC K33NW Pad
Location #: 334632



Jun 30, 2023 at 10:05:52 AM
CO

**Photo # 2255 Lack of stabilization/erosion on
cutslope along lease road**