

**Inspection Photos**  
**Location Name: CAERUS PICEANCE LLC K33NW Pad**  
**Location #: 334632**



**Photo # 2206 From entrance to location**



**Photo # 2207 From entrance to location**

**Inspection Photos**  
**Location Name: CAERUS PICEANCE LLC K33NW Pad**  
**Location #: 334632**



**Photo # 2208 From entrance to location**



**Photo # 2209 Location**





**Inspection Photos**  
**Location Name: CAERUS PICEANCE LLC K33NW Pad**  
**Location #: 334632**



**Photo # 2210 Location**



**Photo # 2211 Location**

## Inspection Photos

Location Name: CAERUS PICEANCE LLC K33NW Pad

Location #: 334632



Jun 30, 2023 at 9:04:28 AM  
CO

Photo # 2212 Location



Jun 30, 2023 at 9:45:41 AM  
CO

Photo # 2218 Location



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



**Inspection Photos**  
**Location Name: CAERUS PICEANCE LLC K33NW Pad**  
**Location #: 334632**



**Photo # 2223 Debris**



**Photo # 2226 Debris & stained gravel**





## Inspection Photos

Location Name: CAERUS PICEANCE LLC K33NW Pad

Location #: 334632



Photo # 2246 Debris



Photo # 2225 Stained gravel in secondary containment



**Inspection Photos**  
**Location Name: CAERUS PICEANCE LLC K33NW Pad**  
**Location #: 334632**



**Photo # 2227 Stained gravel in secondary containment**



**Photo # 2232 Stained soils & gravel on location**



# Inspection Photos

Location Name: CAERUS PICEANCE LLC K33NW Pad  
Location #: 334632



Photo # 2243 Debris




Photo # 2216