

Inspection Photos
Location Name: Burr FD Pad 23-219 HN
Location ID: 440510



Lease road entrance sign



Wellheads

Inspection Photos
Location Name: Burr FD Pad 23-219 HN
Location ID: 440510



Production facility



Stained soil

Inspection Photos
Location Name: Burr FD Pad 23-219 HN
Location ID: 440510



Colorado Oil & Gas Conservation Commission
40.46634, -104.83293, 1448.1m, 116°
07/05/2023 10:36:02

Stained soil



Colorado Oil & Gas Conservation Commission
40.46669, -104.83293, 1428.4m, 350°
07/05/2023 10:38:57

Unused equipment

Inspection Photos
Location Name: Burr FD Pad 23-219 HN
Location ID: 440510



Trash and weeds



Chemical system placards

Inspection Photos
Location Name: Burr FD Pad 23-219 HN
Location ID: 440510



300 bbl crude oil maintenance tank placards