

Inspection Photos
Location Name: CAERUS PICEANCE LLC L4E Pad
Location #: 323955



Photo # 2321 From entrance to location



Photo # 2322 From entrance to location

Inspection Photos
Location Name: CAERUS PICEANCE LLC L4E Pad
Location #: 323955



Photo # 2323 Location



Photo # 2324 Location



Inspection Photos
Location Name: CAERUS PICEANCE LLC L4E Pad
Location #: 323955



Photo # 2325 Location



Photo # 2326 Location

Inspection Photos
Location Name: CAERUS PICEANCE LLC L4E Pad
Location #: 323955



Photo # 2328 Flowline heating insulation open ended/wildlife hazard



Photo # 2332 Stained soils & gravel

Inspection Photos
Location Name: CAERUS PICEANCE LLC L4E Pad
Location #: 323955



Photo # 2333 Debris



Photo # 2338 Unmarked deadman