

Inspection Photos

6/28/2023

Operator: CAERUS PICEANCE LLC #10456

Location Number: 458475

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location Number: 458475



June 28, 2023



June 28, 2023

Photo 1: Photos taken from the east end of the Location. Photo shows produced water tank stored on the Location without required labeling pursuant to Rule 605.h. Tank also lacks spill containment BMPs. Tank also appears to be unused.

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location Number: 458475



June 28, 2023



June 28, 2023

Photo 2: Photos of porta-john on the west end of the Location. Stake/strap used to secure porta-john is not longer in proper functioning condition. BMPs to prevent/contain a spill missing or insufficient.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location Number: 458475



June 28, 2023



June 28, 2023

Photo 3: Photos 3-4 examples of various unused equipment observed throughout the Location.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location Number: 458475



Photo 4: See comments under photo 3.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location Number: 458475



Photo 5: Stained soils at separator equipment and north end of the Location.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location Number: 458475



Photo 6: Photos examples showing pipes/lines at separator equipment not properly capped.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location Number: 458475



Photo 7: Photos examples showing pipes/lines at separator equipment not properly capped.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location Number: 458475



Photo 8: Fence on the east end of the Location has been pushed over. Maintenance advised.

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location Number: 458475



Photo 9: Photo example showing interim areas of the Location. Vegetation observed in the photo is predominantly annual grass species, and does not contribute towards 1003, 80% uniform perennial vegetative requirements.



Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location Number: 458475



Photo 8: Wells missing required signage.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location Number: 458475



Photo 9: Tank battery facility missing required signage.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location Number: 458475



Photo 10: Soil stockpiles on Location missing BMPs per 1002.c

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location Number: 458475



Photo 11: Stockpile on southwest end of the Location.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location Number: 458475



Photo 12: Photo shows mobile heater equipment stored on Location. Equipment not necessary for production. Photo also example showing example stained soils observed around the heater, wellheads, and gas lift equipment currently active on the Location.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location Number: 458475



Photo 13: Stained soils around battery and separator equipment.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location Number: 458475



Photo 14: Containment BMP at the Gas Lift equipment with fluids.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location Number: 458475



Photo 15: Photos 15-16 examples showing lines/pipe at and around the separator equipment not properly capped.

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location Number: 458475



Photo 16: See comments under photo 15.

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location Number: 458475



Photo 17: Photos examples showing areas where erosion logs appear to have been lifted during maintenance work, and placed back onto the surface. BMP has not been installed per good engineering practice (trenched/backfilled).

Inspection Photos
Operator Name: CAERUS PICEANCE LLC #10456
Location Number: 458475



Photo 18: Sediment trap and outlet on west end of the Location.

Inspection Photos

Operator Name: CAERUS PICEANCE LLC #10456

Location Number: 458475



Photo 19: Photos examples showing erosion logs that have been compressed/flattened, and no longer in proper functioning condition.