



99999999

STATE OF COLORADO
GAS CONSERVATION COMMISSION

DEPARTMENT OF NATURAL RESOURCES

RECEIVED
APR 16 1981
COLO. OIL & GAS CONS. COMM.

File in duplicate for Patented and Federal lands.
File in triplicate for State lands.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION & SERIAL NO.	
2. NAME OF OPERATOR BWAB Incorporated		6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
3. ADDRESS OF OPERATOR 7935 E. Prentice Ave., 40 DTC West, Englewood, CO 80111		7. UNIT AGREEMENT NAME	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface NW NE Sec. 2-T7N-R54W At proposed prod. zone		8. FARM OR LEASE NAME Van Gundy	
14. PERMIT NO. 64-471		9. WELL NO. #1-A	
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4242' KB		10. FIELD AND POOL, OR WILDCAT Pawnee Creek	
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec. 2-T7N-R54W	
		12. COUNTY Logan	13. STATE CO

660fn!
1980 fel

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREAT

MULTIPLE COMPLETE

FRACTURE TREATMENT

ALTERING CASING

SHOOT OR ACIDIZE

ABANDON

SHOOTING OR ACIDIZING

ABANDONMENT*

REPAIR WELL

CHANGE PLANS:

(Other)

(Other)

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

18. Date of work March, 1981

* Must be accompanied by a cement verification report.

The Van Gundy #1-A was plugged & abandoned on 3/16/81 as follows: Sand was used to fill the casing from PBTD to 5020' & capped with 5 sx. cement. The 4½" casing was pulled to 3778'. Twenty sx. of cement was placed between 160'-115' & filled with mud to 30' & then a 10 sx. plug was placed 3' below ground level. The head was cut off & a cap welded on.

** Attachment

EXHAUSTED
OIL WELL

DVR	
FJP	
MHM	<input checked="" type="checkbox"/>
JAM	<input checked="" type="checkbox"/>
JJD	<input checked="" type="checkbox"/>
MLS	
COM	

19. I hereby certify that the foregoing is true and correct

SIGNED Robert C. Arceneaux
Robert C. Arceneaux

TITLE Operations Mgr.

DATE 4/15/81

(This space for Federal or State office use)

APPROVED BY [Signature]
CONDITIONS OF APPROVAL, IF ANY:

TITLE DIRECTOR
O & G Cons. Comm.

DATE APR 27 1981



00382005