

VISION ENERGY LLC, FEDERAL-68S97W/30SWSW

Location #312470

Date: 7/3/2023



NE Corner of Location – Photo #04947

NW Corner of Location – Photo #04948

VISION ENERGY LLC, FEDERAL-68S97W/30SWSW

Location #312470

Date: 7/3/2023



SW Corner of Location – Photo #04949

SE Corner of Location – Photo #04950

VISION ENERGY LLC, FEDERAL-68S97W/30SWSW

Location #312470

Date: 7/3/2023



Wellhead/Weeds – Photo #04953

Separator/Weeds – Photo #04955

VISION ENERGY LLC, FEDERAL-68S97W/30SWSW

Location #312470

Date: 7/3/2023



Separator/Weeds – Photo #04956



Unsecured Gas Meter/Weeds – Photo #04958

VISION ENERGY LLC, FEDERAL-68S97W/30SWSW

Location #312470

Date: 7/3/2023



Debris – Photo #04951



Location Lacks Stabilization – Photo #04960

VISION ENERGY LLC, FEDERAL-68S97W/30SWSW

Location #312470

Date: 7/3/2023



Location Lacks Stabilization – Photo #04952



Insufficient Vehicle Tracking BMPs at Location Entrance/Exit – Photo #04961

VISION ENERGY LLC, FEDERAL-68S97W/30SWSW

Location #312470

Date: 7/3/2023



**Lease Road Passes Through Unprotected Creek Bed
– Photo #04965**



**Lease Road Passes Through Unprotected Creek Bed
– Photo #04966**