

VISION ENERGY LLC, FEDERAL-68S98W/35SENW

Location #312511

Date: 7/3/2023



Southern Entrance to Location – Photo #04969

Wellhead/Missing Sign – Photo #04970

VISION ENERGY LLC, FEDERAL-68S98W/35SENW

Location #312511

Date: 7/3/2023



Debris – Photo #04971



Unused Gas Meter – Photo #04975

VISION ENERGY LLC, FEDERAL-68S98W/35SENW

Location #312511

Date: 7/3/2023



Weeds in Pit/No Permit on Record for Pit – Photo #04973

Weeds in Pit/No Permit on Record for Pit – Photo #04974

VISION ENERGY LLC, FEDERAL-68S98W/35SE1W

Location #312511

Date: 7/3/2023



**Access Road Crosses Unprotected Creek Bed –
Photo #04977**

**Access Road Crosses Unprotected Creek Bed –
Photo #04978**