

Inspection Photos
Location Name: Enduring West Animas 7U-3
Location ID: 067-08706



Photo #1. Overview of the well location.

Inspection Photos
Location Name: Enduring West Animas 7U-3
Location ID: 067-08706




Photo #2. View of the wellhead assembly.