

# Interim and Stormwater Inspection

June 30, 2023

Operator: KP Kauffman Company Inc # 46290

Location ID: 318020

Inspection Document #:709400344

Weld, County

NWNE, Section 24, 2N63W

Reed Wold  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Cuykedal C 3  
Location ID: 318020



Photo 1. Photo of sign on site.



Photo 2. Photo of Weeds on site.

**Inspection Photos**  
**Location Name: Cuykedal C 3**  
**Location ID: 318020**



**Photo 3. Photo taken of weeds in and around tank battery**



**Photo 4. See Photo 3 comments.**



**Inspection Photos**  
**Location Name: Cuykedal C 3**  
**Location ID: 318020**



**Photo 5. Photo taken of weeds in and around fenced in valves.**



**Photo 6. See Photo 5 comments.**

**Inspection Photos**  
**Location Name: Cuykedal C 3**  
**Location ID: 318020**



**Photo 7. Photo taken of weeds in access road and reclaimed area.**



**Photo 8. Photo taken of separator and access road weeds.**



**Inspection Photos**  
**Location Name: Cuykedal C 3**  
**Location ID: 318020**



**Photo 9. Photo taken of weeds throughout site and equipment.**



**Photo 10. Photo taken of separator area.**

Inspection Number: 709400344

Inspection Photos  
Location Name: Cuykedal C 3  
Location ID: 318020



Photo 11. Photo taken of location sign at separator.



Photo 12. Photo taken of dead grass from over spraying.



Inspection Photos  
Location Name: Cuykedal C 3  
Location ID: 318020




Photo 13. Photo taken of Well head sign.



Photo 14. Photo taken of weeds around wellhead  
adn in reclaimed area.