

Inspection Photos
Location Name: Middlepark 18 PAD
Location ID: 442024



Photo 1 – Sign at Entrance



Photo 2 – East Tank Battery

Inspection Photos
Location Name: Middlepark 18 PAD
Location ID: 442024



Photo 3 – East Tank Battery



Photo 4 – Gas Meter and Pig Station

Inspection Photos
Location Name: Middlepark 18 PAD
Location ID: 442024



Photo 5 – ECD



Photo 6 – Tank Battery

Inspection Photos
Location Name: Middlepark 18 PAD
Location ID: 442024



Photo 7 – VRTs



Photo 8 – VRU



Inspection Photos
Location Name: Middlepark 18 PAD
Location ID: 442024



Photo 9 – Separators



Photo 10 – State Seventy Holes J-18 TA Wellhead

Inspection Photos
Location Name: Middlepark 18 PAD
Location ID: 442024



Photo 11 – Trash on North Side of Location



Photo 12 – Trash on North Side Location

Inspection Photos
Location Name: Middlepark 18 PAD
Location ID: 442024



Photo 13 – Trash on the North Side of Location