

Interim and Stormwater Inspection

June 26, 2023

Operator: KP Kauffman Company Inc # 46290

Location ID: 317790

Inspection Document #:709400349

Weld, County

SESE, Section 17, 2N66W

Reed Wold
Reclamation Specialist, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: NESSSU Tank Battery
Location ID: 317790



Photo 1. Photo of sign on site.



Photo 2. Photo of weeds in and on tank battery berm.

Inspection Photos
Location Name: NESSSU Tank Battery
Location ID: 317790



Photo 3. Photo taken of weeds and unused equipment (culvert) on site.



Photo 4. Secondary container filled with water with no wildlife netting to keep animals from drowning.

