

# Interim and Stormwater Inspection

June 26, 2023

Operator: Kerr McGee Oil & Gas # 47120

Location ID: 318587

Inspection Document #:709400351

Weld, County

NENE, Section 20, 2N66W

Reed Wold  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: Schmidt Paul "B" GU #1  
Location ID:318587



Photo 1. Photo taken of Location sign.



Photo 2. Photo taken of tank battery.



**Inspection Photos**  
**Location Name: Schmidt Paul "B" GU #1**  
**Location ID:318587**



**Photo 3. Photo taken of erosion onsite from stormwater run off.**



**Photo 4. Photo of weeds on site..**

Inspection Number: 7094001351



Inspection Photos  
Location Name: Schmidt Paul "B" GU #1  
Location ID:318587



Photo 5. Photo taken of Unused equipment on site.

