



00197274

WELL SITE INSPECTION FORM

LOCATION SUNE 25 - GN - 67W
OPERATOR Nautilus Equip. Co.
WELL NAME Long #2

FIELD La Poudre South
COUNTY Weld
PERMIT # 87-714

DATE OF INSPECTION DURING DRILLING: 10/6/87

RIG Equity SURFACE CASING: 8 5/8 DEPTH: 216 KB
BOP'S _____ RETURNS: good WOC: 8
CONTACT _____ CMT VOL: _____

ADEQUATE AQUIFER PROTECTION? _____

COMMENTS 10/6 Drlg sat hole (trouble w/ shallow gravel)
10/22 Set pipe - ready to move rig to Ft Morgan

DATE OF INSPECTION AFTER COMPLETION: _____

FRACED: YES _____ NO _____ PRODUCTION STRING: _____

WATER DISPOSAL: PITS _____, INJECTED _____, COMMERCIAL _____, UNKNOWN _____, N.A. _____

PITS: PERMIT Y _____ N _____, SKIM TANK Y _____ N _____, DIMENSIONS _____ GALLONS

LEASE SIGN: YES _____ NO _____ TANK ID: YES _____ NO _____ NA _____ FENCED: YES _____ NO _____

SURFACE EQUIPMENT: _____

COMMENTS: _____

DATE OF P&A INSPECTION _____

PITS BACKFILLED: YES _____ NO _____ SURFACE RECLAIMED: YES _____ NO _____

HOLE MARKER: YES _____ NO _____ SITE CLEAN: YES _____ NO _____

BOND RELEASE OK: YES _____ NO _____ LANDOWNER RELEASE: YES _____ NO _____

COMMENTS: _____

DATE OF SAFETY INSPECTION _____

COMMENTS: _____

INSPECTOR SP

API No. _____

P&A Inspected: Yes _____ No _____